

Inspection Photos

03/23/2017

Operator: Longhorn Supply Co #51140

Location ID: 405003

Inspection Doc. Number: 682501832

Weld County, CO

SESW Section 26 T7N R59W

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: Longhorn Supply Co
Location ID: 405003



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: Longhorn Supply Co
Location ID: 405003



Photo 2: Photo of pump jack concrete pad and pipe remaining on location.