

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/13/2017

Submitted Date:

03/29/2017

Document Number:

680301773

**FIELD INSPECTION FORM**

Loc ID 312335 Inspector Name: SCHURE, KYM On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 94300  
Name of Operator: WARD & SON\* ALFRED  
Address: P O BOX 737  
City: OGALLALLA State: NE Zip: 69153

**Findings:**

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Schure, Kym		kym.schure@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288510	WELL	PR	08/05/2008	OG	075-09361	MICHAELS 2	PA

**General Comment:**

Field Inspector drove to location. P&A postponed until 3-15-2017 due to high winds. Plugging contractor contacted by COGCC N.E. Field Office regarding postponement. Approved by Schure

**Inspected Facilities**

Facility ID: 288510 Type: WELL API Number: 075-09361 Status: PR Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: \_\_\_\_\_

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_