

Stormwater Inspection

March 23, 2017

Operator: NOBLE ENERGY INC- #100322

Location ID: 306586

Weld County, CO

NESE Section 12 T6N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Shoemaker /AA07-65HN Multi
Location ID: 306586



Photo 1. Photo taken from the northern battery location, facing East. An unconsolidated berm has been installed along the north and east production area. Cattle have diminished the quality of the berm along major portions.



Photo 2. Photo taken from the northeast battery location. A series of wattles have been placed at the potential discharge point.

Inspection Photos
Location Name: Shoemaker /AA07-65HN Multi
Location ID: 306586



Photo 3. Photo taken from the eastern battery location, facing South. An unconsolidated berm has been installed along the north and east production area. Cattle have diminished the quality of the berm along major portions.



Photo 4. Photo taken from the eastern location, facing North. A remnant wattle was observed within the vegetative plant cover.

Inspection Photos
Location Name: Shoemaker /AA07-65HN Multi
Location ID: 306586



Photo 5. Photo taken from the southeastern battery location, facing North. An unconsolidated berm has been installed along the north and east production area.



Photo 6. Photo taken from the southeastern battery location, facing East. Wattle has been placed at the potential discharge point.

Inspection Photos
Location Name: Shoemaker /AA07-65HN Multi
Location ID: 306586



Photo 7. Photo taken from the southeastern location, facing North. A remnant wattle was observed within the vegetative plant cover.