

Inspection Photos
Location Name: State 36-6
API: 05-123-26639



Photo from prior inspection



Photo 1: Deadman marked

Inspection Photos
Location Name: State 36-6
API: 05-123-26639



Photo 2: Subsidence on drilling pit

Photo 3: Subsidence on drilling pit



Inspection Photos
Location Name: State 36-6
API: 05-123-26639



Photo 4: Stained soil from pump jack

