

Final Reclamation and Stormwater Inspection

March 27, 2017

Operator: CDM OIL & GAS - #14740

API: 05-013-06165

Boulder County, CO

SWNW Section 34 T1N R69W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WEEMS #1-34
API: 05-013-06165



Photo 1. Photo taken from the well location, facing West. All equipment has been removed, did not observe any List A or B Colorado Noxious weeds, and did not observe any stormwater erosion issues.



Photo 2. Photo taken from the well location, facing North. All equipment has been removed, did not observe any List A or B Colorado Noxious weeds, and did not observe any stormwater erosion issues.

Inspection Photos
Location Name: WEEMS #1-34
API: 05-013-06165



Photo 3. Photo taken from the well location, facing East. All equipment has been removed, did not observe any List A or B Colorado Noxious weeds, and did not observe any stormwater erosion issues.



Photo 4. Photo taken from the well location, facing South. All equipment has been removed, did not observe any List A or B Colorado Noxious weeds, and did not observe any stormwater erosion issues.