

Photo#1:

Overview of Location from Entry to NW



March 24, 2017

Photo#2:

View of Early Emerging (cool season) desirable Vegetation which appears Well established in Interim areas.



March 24, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Vanguard JCJ Loc#335521

Photo#3:
Saltcedar / Tamarisk establishing in North Interim area

Photo#4:



March 24, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Vanguard JCJ Loc#335521

Photo#5:

Old Stand desiccated Annual Weeds are breaking off, will blow & become Debris. View at West side of Location



March 24, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Vanguard JCJ Loc#335521