

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2017

Submitted Date:

03/31/2017

Document Number:

680101612**FIELD INSPECTION FORM**

Loc ID 335521	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 5 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																																																																																																							
Operator Information: OGCC Operator Number: <u>10531</u> Name of Operator: <u>VANGUARD OPERATING LLC</u> Address: <u>5847 SAN FELIPE #3000</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77057</u>																																																																																																																																											
Contact Information: <table border="1" style="width:100%"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Pearl, Chase</td> <td></td> <td>cpearl@vnrlc.com</td> <td>Reclamation</td> </tr> <tr> <td></td> <td></td> <td>aaxelson@vnrlc.com</td> <td></td> </tr> <tr> <td>Ghan, Scott</td> <td>970 876-1959</td> <td>sgghan@vnrlc.com</td> <td></td> </tr> </table>					Contact Name	Phone	Email	Comment	Pearl, Chase		cpearl@vnrlc.com	Reclamation			aaxelson@vnrlc.com		Ghan, Scott	970 876-1959	sgghan@vnrlc.com																																																																																																																								
Contact Name	Phone	Email	Comment																																																																																																																																								
Pearl, Chase		cpearl@vnrlc.com	Reclamation																																																																																																																																								
		aaxelson@vnrlc.com																																																																																																																																									
Ghan, Scott	970 876-1959	sgghan@vnrlc.com																																																																																																																																									
Inspected Facilities: <table border="1" style="width:100%"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>297301</td><td>WELL</td><td>PR</td><td>04/22/2009</td><td>GW</td><td>045-16382</td><td>JCJ 22C-21-692</td><td>RI</td></tr> <tr><td>297476</td><td>WELL</td><td>PR</td><td>04/08/2009</td><td>GW</td><td>045-16854</td><td>JCJ 11A-21-692</td><td>RI</td></tr> <tr><td>297477</td><td>WELL</td><td>PR</td><td>04/20/2009</td><td>GW</td><td>045-16855</td><td>JCJ 21B-21-692</td><td>RI</td></tr> <tr><td>297478</td><td>WELL</td><td>PR</td><td>04/20/2009</td><td>GW</td><td>045-16856</td><td>JCJ 21A-21-692</td><td>RI</td></tr> <tr><td>297479</td><td>WELL</td><td>PR</td><td>03/26/2009</td><td>GW</td><td>045-16857</td><td>JCJ 12D-21-692</td><td>RI</td></tr> <tr><td>297480</td><td>WELL</td><td>PR</td><td>03/25/2009</td><td>GW</td><td>045-16858</td><td>JCJ 12C-21-692</td><td>RI</td></tr> <tr><td>297481</td><td>WELL</td><td>PR</td><td>03/26/2009</td><td>GW</td><td>045-16859</td><td>JCJ 12B-21-692</td><td>RI</td></tr> <tr><td>297482</td><td>WELL</td><td>PR</td><td>03/30/2009</td><td>GW</td><td>045-16860</td><td>JCJ 12A-21-692</td><td>RI</td></tr> <tr><td>297483</td><td>WELL</td><td>PR</td><td>04/09/2009</td><td>GW</td><td>045-16861</td><td>JCJ 11D-21-692</td><td>RI</td></tr> <tr><td>297484</td><td>WELL</td><td>PR</td><td>04/09/2009</td><td>GW</td><td>045-16862</td><td>JCJ 11C-21-692</td><td>RI</td></tr> <tr><td>297485</td><td>WELL</td><td>PR</td><td>03/25/2009</td><td>GW</td><td>045-16863</td><td>JCJ 11B-21-692</td><td>RI</td></tr> <tr><td>297486</td><td>WELL</td><td>PR</td><td>04/22/2009</td><td>GW</td><td>045-16864</td><td>JCJ 22D-21-692</td><td>RI</td></tr> <tr><td>297487</td><td>WELL</td><td>PR</td><td>04/22/2009</td><td>GW</td><td>045-16865</td><td>JCJ 22B-21-692</td><td>RI</td></tr> <tr><td>297488</td><td>WELL</td><td>PR</td><td>04/09/2009</td><td>GW</td><td>045-16866</td><td>JCJ 22A-21-692</td><td>RI</td></tr> <tr><td>297489</td><td>WELL</td><td>PR</td><td>04/08/2009</td><td>GW</td><td>045-16867</td><td>JCJ 21D-21-692</td><td>RI</td></tr> <tr><td>297490</td><td>WELL</td><td>PR</td><td>04/13/2009</td><td>GW</td><td>045-16868</td><td>JCJ 21C-21-692</td><td>RI</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	297301	WELL	PR	04/22/2009	GW	045-16382	JCJ 22C-21-692	RI	297476	WELL	PR	04/08/2009	GW	045-16854	JCJ 11A-21-692	RI	297477	WELL	PR	04/20/2009	GW	045-16855	JCJ 21B-21-692	RI	297478	WELL	PR	04/20/2009	GW	045-16856	JCJ 21A-21-692	RI	297479	WELL	PR	03/26/2009	GW	045-16857	JCJ 12D-21-692	RI	297480	WELL	PR	03/25/2009	GW	045-16858	JCJ 12C-21-692	RI	297481	WELL	PR	03/26/2009	GW	045-16859	JCJ 12B-21-692	RI	297482	WELL	PR	03/30/2009	GW	045-16860	JCJ 12A-21-692	RI	297483	WELL	PR	04/09/2009	GW	045-16861	JCJ 11D-21-692	RI	297484	WELL	PR	04/09/2009	GW	045-16862	JCJ 11C-21-692	RI	297485	WELL	PR	03/25/2009	GW	045-16863	JCJ 11B-21-692	RI	297486	WELL	PR	04/22/2009	GW	045-16864	JCJ 22D-21-692	RI	297487	WELL	PR	04/22/2009	GW	045-16865	JCJ 22B-21-692	RI	297488	WELL	PR	04/09/2009	GW	045-16866	JCJ 22A-21-692	RI	297489	WELL	PR	04/08/2009	GW	045-16867	JCJ 21D-21-692	RI	297490	WELL	PR	04/13/2009	GW	045-16868	JCJ 21C-21-692	RI
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																																				
297301	WELL	PR	04/22/2009	GW	045-16382	JCJ 22C-21-692	RI																																																																																																																																				
297476	WELL	PR	04/08/2009	GW	045-16854	JCJ 11A-21-692	RI																																																																																																																																				
297477	WELL	PR	04/20/2009	GW	045-16855	JCJ 21B-21-692	RI																																																																																																																																				
297478	WELL	PR	04/20/2009	GW	045-16856	JCJ 21A-21-692	RI																																																																																																																																				
297479	WELL	PR	03/26/2009	GW	045-16857	JCJ 12D-21-692	RI																																																																																																																																				
297480	WELL	PR	03/25/2009	GW	045-16858	JCJ 12C-21-692	RI																																																																																																																																				
297481	WELL	PR	03/26/2009	GW	045-16859	JCJ 12B-21-692	RI																																																																																																																																				
297482	WELL	PR	03/30/2009	GW	045-16860	JCJ 12A-21-692	RI																																																																																																																																				
297483	WELL	PR	04/09/2009	GW	045-16861	JCJ 11D-21-692	RI																																																																																																																																				
297484	WELL	PR	04/09/2009	GW	045-16862	JCJ 11C-21-692	RI																																																																																																																																				
297485	WELL	PR	03/25/2009	GW	045-16863	JCJ 11B-21-692	RI																																																																																																																																				
297486	WELL	PR	04/22/2009	GW	045-16864	JCJ 22D-21-692	RI																																																																																																																																				
297487	WELL	PR	04/22/2009	GW	045-16865	JCJ 22B-21-692	RI																																																																																																																																				
297488	WELL	PR	04/09/2009	GW	045-16866	JCJ 22A-21-692	RI																																																																																																																																				
297489	WELL	PR	04/08/2009	GW	045-16867	JCJ 21D-21-692	RI																																																																																																																																				
297490	WELL	PR	04/13/2009	GW	045-16868	JCJ 21C-21-692	RI																																																																																																																																				

General Comment:

This is an Interim Reclamation and Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed are still applicable. Inspection was prompted by Request from Operator for Interim Reclamation Inspection.

Inspected Facilities				
Facility ID: <u>297301</u>	Type: <u>WELL</u>	API Number: <u>045-16382</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>297476</u>	Type: <u>WELL</u>	API Number: <u>045-16854</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>297477</u>	Type: <u>WELL</u>	API Number: <u>045-16855</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>297478</u>	Type: <u>WELL</u>	API Number: <u>045-16856</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>297479</u>	Type: <u>WELL</u>	API Number: <u>045-16857</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>297480</u>	Type: <u>WELL</u>	API Number: <u>045-16858</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>297481</u>	Type: <u>WELL</u>	API Number: <u>045-16859</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>297482</u>	Type: <u>WELL</u>	API Number: <u>045-16860</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>297483</u>	Type: <u>WELL</u>	API Number: <u>045-16861</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>297484</u>	Type: <u>WELL</u>	API Number: <u>045-16862</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>297485</u>	Type: <u>WELL</u>	API Number: <u>045-16863</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>297486</u>	Type: <u>WELL</u>	API Number: <u>045-16864</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>297487</u>	Type: <u>WELL</u>	API Number: <u>045-16865</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>297488</u>	Type: <u>WELL</u>	API Number: <u>045-16866</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>297489</u>	Type: <u>WELL</u>	API Number: <u>045-16867</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>297490</u>	Type: <u>WELL</u>	API Number: <u>045-16868</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Pasture**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? PassProduction areas stabilized ? Pass1003c. Compacted areas have been cross ripped? Pass1003d. Drilling pit closed? PassSubsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? InProduction areas have been stabilized? PassSegregated soils have been replaced? Pass**RESTORATION AND REVEGETATION**Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-CroplandTop soil replaced PassRecontoured Pass80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? I

Comment

Electric Fencing has been used to exclude Livestock. Emerging Vegetation appears robust & Well established. There are old stand annual weeds scattered throughout Interim areas; one area of heavy growth area around edge of facilities are becoming Debris. A few (4-5) Salt Cedar/Tamarisk , a B List Noxious Weed are establishing in North Interim area. One desiccated/old growth Knapweed plant was noted. An inspection later in the growing season when all species have emerged would be needed to determine if Site can PASS Interim Reclamation.

Corrective Action

Control B List Weed, Tamarisk /Saltcedar, consulting County Vegetation Manager for control methods & timing of Controls. Clean/Remove Desiccated Annual Weeds that are becoming Debris. Refer to Photos attached for Detail.

Date 05/01/2017Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____Contoured _____Culverts removed _____Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: Corrective Action:

Date _____

Overall Final Reclamation

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Drains	Pass					
Berms	Pass					
Seeding	Pass					
Compaction	Pass					

Comment: Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680101633	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113413