

Inspection Photos
Location Name: Hebron 02-07H
API: 05-057-06499



Photo 1. View of location at entrance facing northwest.



Photo 2. Ongoing remediation of historic spill and tubing stored at wellhead.

Inspection Photos
Location Name: Hebron 02-07H
API: 05-057-06499



Photo 3. Portable containment stored on location.



Photo 4. One of many places where silt fence has fallen down.