

Inspection Photos
Location Name: Hebron 1-18H
Location ID: 414127



Photo 1. View of location at entrance facing southwest.



Photo 2. Broken portapotty sitting in snowmelt.

Inspection Photos
Location Name: Hebron 1-18H
Location ID: 414127



Photo 3. Open rathole.



Photo 4. Subsidence with sheen on top of water.

Inspection Photos
Location Name: Hebron 1-18H
Location ID: 414127



Photo 5. Unlabeled containers without secondary containment sitting in snowmelt.



Photo 6. Low spot in berm.