



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner facing southward. Revegetation is largely comprised of grasses such as western wheatgrass (*Pascopyrum smithii*) and Indian ricegrass (*Achnatherum hymenoides*), and dropseed (*Sporobolus* sp.).



Photo 3: View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 4: View of musk thistles within the project area.



Photo 5: View of Russian knapweed (*Acroptilon repens*) from the previous growing season within the southern portion of the project area.



Photo 6: View of area along the access road where concentrated stormwater flows are eroding the sides of the access road.