

Inspection Photos

03/31/2017

Operator: Whiting Oil and Gas #96155

Location ID: 444459

Inspection Doc. Number: 682501839

Weld County, CO

SESW Section 25 T10N R58W

Aaron Trujillo

Reclamation Specialist

COGCC





Photo 1: Photo taken from the west end of the location, facing west. Photo shows sediment trap has had additional inlet and outlet protection implemented and appears to be sufficient and in proper functioning condition.



Photo 2: Photo taken from the west end of the location, facing west. Photo shows sediment trap has had additional inlet and outlet protection implemented and appears to be sufficient and in proper functioning condition.