

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/04/2017

Submitted Date:

04/04/2017

Document Number:

666803083**FIELD INSPECTION FORM**

Loc ID 335354 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264878	WELL	PR	02/23/2003	GW	045-08955	BENZEL 36-2D (B36X)	PR
264879	WELL	PR	02/19/2003	GW	045-08956	BENZEL 36-2C (B36X)	PR
264880	WELL	PR	02/27/2003	GW	045-08957	BENZEL 36-1B (B36X)	PR
264887	WELL	PR	02/19/2003	GW	045-08963	BENZEL 36-7B (B36X)	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Heated Separator

# 4

Comment: Corrective Action: Date: 

Type: Gas Meter Run

# 1

Comment: Corrective Action: Date: 

Type: Plunger Lift

# 4

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment: Centralized battery						
Corrective Action: <input type="text"/>						Date: <input type="text"/>

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance	
Comment:								
Corrective Action:							Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS	
CONDENSATE		2	300 BBLS	STEEL AST			39.489435,-107.721231	
Comment:								

Corrective Action:		Date:	
<b>Paint</b>			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
<b>Berms</b>			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Metal	Adequate	Walls Sufficient	Base Sufficient
Comment:			
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 264878 Type: WELL API Number: 045-08955 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 264879 Type: WELL API Number: 045-08956 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 264880 Type: WELL API Number: 045-08957 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 264887 Type: WELL API Number: 045-08963 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
		Ditches	Pass			
		Gravel	Pass			
Gravel	Pass					
Seeding	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT