

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2017

Submitted Date:

03/28/2017

Document Number:

674703783**FIELD INSPECTION FORM**

Loc ID 335560	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>				Findings: <u>24</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284554	WELL	PR	05/02/2006	GW	045-12211	N.PARACHUTE MF02C D09A 696	PR
284555	WELL	PR	09/01/2007	GW	045-12210	N.PARACHUTE MF02A D09A 696	PR
284556	WELL	PR	03/28/2007	GW	045-12209	N. PARACHUTE MF20C D09A696	PR
284557	WELL	PR	05/02/2006	GW	045-12208	N.PARCHUTE MF07C D09A 696	PR
284558	WELL	PR	01/27/2014	GW	045-12207	N.PARACHUTE MF07A D09A 696	PR
284559	WELL	PR	05/02/2006	GW	045-12206	N.PARACHUTE MF06C D09A 696	PR
284560	WELL	PR	11/10/2007	GW	045-12205	N.PARACHUTE MF 05B D09A 696	PR
289509	WELL	PR	02/28/2007	GW	045-13793	N. PARACHUTE MF20A D09A 696	PR
297094	WELL	PR	06/01/2009	GW	045-16299	N. PARACHUTE MF02B-9 D09A 69	PR
297095	WELL	PR	04/28/2009	GW	045-16300	N. PARACHUTE MF03C-9 D09A 69	PR
297096	WELL	PR	04/29/2009	GW	045-16301	N. PARACHUTE MF03A-9 D09A 69	PR
297097	WELL	PR	05/09/2009	GW	045-16302	N. PARACHUTE MF03D-9 D09A 69	PR
297099	WELL	PR	01/27/2014	GW	045-16304	N. PARACHUTE MF04D-9 D09A 69	PR
297100	WELL	PR	04/09/2009	GW	045-16305	N. PARACHUTE MF04A-9 D09A 69	PR
297101	WELL	PR	06/01/2009	GW	045-16306	N. PARACHUTE MF04C-9 D09A 69	PR
299810	WELL	PR	07/03/2009	GW	045-17757	N. PARACHUTE MF06B-9 D09A 69	PR

299811	WELL	PR	06/29/2009	GW	045-17758	N. PARACHUTE MF06C-9 D09A 69	PR
299812	WELL	PR	07/03/2009	GW	045-17759	N. PARACHUTE MF05D-9 D09A 69	PR
299813	WELL	PR	06/27/2009	GW	045-17760	N. PARACHUTE MF05B-9 D09A 69	PR

General Comment:

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 800-791-7691

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 19		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 19		
Comment: Gas lift			
Corrective Action:		Date:	

Type: Ancillary equipment	# 3		
Comment:	Chemical containers		
Corrective Action:		Date:	
Type: Gas Meter Run	# 19		
Comment:	sells		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	284554	Type:	WELL	API Number:	045-12211	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284555	Type:	WELL	API Number:	045-12210	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284556	Type:	WELL	API Number:	045-12209	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284557	Type:	WELL	API Number:	045-12208	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284558	Type:	WELL	API Number:	045-12207	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284559	Type:	WELL	API Number:	045-12206	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284560	Type:	WELL	API Number:	045-12205	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	289509	Type:	WELL	API Number:	045-13793	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID: 297094	Type: WELL	API Number: 045-16299	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 297095	Type: WELL	API Number: 045-16300	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 297096	Type: WELL	API Number: 045-16301	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 297097	Type: WELL	API Number: 045-16302	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 297099	Type: WELL	API Number: 045-16304	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 297100	Type: WELL	API Number: 045-16305	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 297101	Type: WELL	API Number: 045-16306	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 299810	Type: WELL	API Number: 045-17757	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID:	299811	Type:	WELL	API Number:	045-17758	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	299812	Type:	WELL	API Number:	045-17759	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	299813	Type:	WELL	API Number:	045-17760	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Gravel	Pass			
Berms	Pass					
		Ditches	Pass			
		Culverts	Pass			
Compaction	Pass					
				Material Handling And Spill Prevention	Pass	
Seeding	Pass					
Ditches	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401245704	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110768