

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/30/2017

Submitted Date:

03/31/2017

Document Number:

672500480**FIELD INSPECTION FORM**

Loc ID 448213	Inspector Name: Gomez, Jason	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>10459</u> Name of Operator: <u>EXTRACTION OIL &amp; GAS LLC</u> Address: <u>370 17TH STREET SUITE 5300</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>Findings:</b> <u>2</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		COGCCinspections@extracti onog.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448299	WELL	DG	12/02/2016		123-43845	Mickey 12	WO
448300	WELL	DG	11/30/2016		123-43846	Mickey 9	WO
448301	WELL	DG	12/01/2016		123-43847	Mickey 10	WO
448302	WELL	DG	12/01/2016		123-43848	Mickey 11	WO
448303	WELL	DG	11/28/2016		123-43849	Mickey 6	WO
448304	WELL	DG	11/19/2016		123-43850	Mickey 2	WO
448305	WELL	DG	11/18/2016		123-43851	Mickey 4	WO
448306	WELL	DG	11/19/2016		123-43852	Mickey 3	WO
448307	WELL	DG	11/20/2016		123-43853	Mickey 1	WO
448308	WELL	DG	12/03/2016		123-43854	Mickey 13	WO
448309	WELL	DG	11/18/2016		123-43855	Mickey 5	WO
448310	WELL	DG	11/29/2016		123-43856	Mickey 8	WO
448625	WELL	DG	01/04/2016		123-43947	Mickey 6-Z	WO

**General Comment:**

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	#		corrective date
Comment:	TEMPARARY SOUND WALLS AROUND LOCATION FOR SOUND MITIGATION		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 448299 Type: WELL API Number: 123-43845 Status: DG Insp. Status: WO

**Complaint**

Comment: Complaint #: 200441252

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 3-28-2017 Time 1730Hrs

Contacted by Inspector:

Date: 3-29-2017 Time 1000 Hrs

Well Number#: Location #: 430411/448213

Inspection Document #: 672500480/672500479

Complainant: Clyde Hutchins Phone: 970-567-8748

Address: 3937 Valley Crest Drive Timnath, CO 80547

Nature of complaint: Noise

Field Inspector Actions:

On 3-28-2017, I was contacted by James Precup NE supervisor of the COGCC in reference to a noise complaint at the residence of the complainant Clyde Hutchins 3937 Valley Crest Drive Timnath CO 80547.

I contacted the complainant and he indicated he had been experiencing noise an annoying sound coming from the Extraction locations which were located approx. 2 miles away to the SE of his home. The complainant stated the noise occurred during the nighttime at different times.

I performed a site inspection at the locations indicated by the complainant. See inspection doc# 672500480/672500479 for results of site inspections.

I contacted Extractions Josh Carlisle to get the sound study results from the times the complaint had experienced the noise to check for any possible compliance issues. All information from the studies and the site inspection were directed to the complaint specialist for further review.

At the time of inspection, no violations of COGCC rules were observed.

Corrective Action:

Date:

**Well Stimulation**

Stimulation Company: LIBERTY

Stimulation Type: HYDRAULIC FRAC

**Observation:**

Other: \_\_\_\_\_

Maximum Casing Recorded: \_\_\_\_\_ PSI

Tubing: \_\_\_\_\_

Surface: \_\_\_\_\_

Intermediate: \_\_\_\_\_

Production: \_\_\_\_\_

Instantaneous Shut-In Pressure (ISIP) 4500

Bradenhead Psi: \_\_\_\_\_

Frac Flow Back: Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 448300	Type: WELL	API Number: 123-43846	Status: DG	Insp. Status: WO
Facility ID: 448301	Type: WELL	API Number: 123-43847	Status: DG	Insp. Status: WO
Facility ID: 448302	Type: WELL	API Number: 123-43848	Status: DG	Insp. Status: WO
Facility ID: 448303	Type: WELL	API Number: 123-43849	Status: DG	Insp. Status: WO
Facility ID: 448304	Type: WELL	API Number: 123-43850	Status: DG	Insp. Status: WO
Facility ID: 448305	Type: WELL	API Number: 123-43851	Status: DG	Insp. Status: WO
Facility ID: 448306	Type: WELL	API Number: 123-43852	Status: DG	Insp. Status: WO
Facility ID: 448307	Type: WELL	API Number: 123-43853	Status: DG	Insp. Status: WO
Facility ID: 448308	Type: WELL	API Number: 123-43854	Status: DG	Insp. Status: WO
Facility ID: 448309	Type: WELL	API Number: 123-43855	Status: DG	Insp. Status: WO
Facility ID: 448310	Type: WELL	API Number: 123-43856	Status: DG	Insp. Status: WO
Facility ID: 448625	Type: WELL	API Number: 123-43947	Status: DG	Insp. Status: WO

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Gravel	Pass					
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Rip Rap	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT