

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2017

Submitted Date:

04/03/2017

Document Number:

672500483**FIELD INSPECTION FORM**

Loc ID 449174 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1801 BROADWAY #500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449164	WELL	XX	02/09/2017		001-09993	Ocho LD 17-367HC	DG
449165	WELL	XX	02/09/2017		001-09994	Ocho LD 17-367HN	DG
449167	WELL	XX	02/09/2017		001-09996	Ocho LD 17-364HC	DG
449172	WELL	XX	02/09/2017		001-10001	Ocho LD 17-365HN	DG

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

#

Comment: APPROX 30' SOUND WALLS ON NORTH, EAST AND WEST SIDE OF LOCATION

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Field Flare

Comment: NOT IN USE AT TIME OF INSPECTION

Corrective Action:

Date:

Inspected Facilities

Facility ID: 449164 Type: WELL API Number: 001-09993 Status: XX Insp. Status: DG

Complaint

Comment: [Complaint #: 200441264 / 200441265 / 200441266](#)

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 3-31-2017 Time 1000 Hrs

Contacted by Inspector:

Date: 4-3-2017 Time 1530 Hrs

Well Number#: Location #: 449174

Inspection Document #: 672500483

Complainant: Lisa Cloutier / Verra Clark / Laurie Jorgensen Phone: 720-271-0946 / 720-261-1844 / 303-835-2918

Address: 6124 E 162nd Ave / 16123 Krameria ct, 6103 E 161st Ave, Brighton CO 80602

Nature of complaint: Noise/Lights/Odors

Field Inspector Actions:

On 4-3-2017, I was contacted by James Precup NE supervisor of the COGCC in reference to a complaint at the residence of the complainants Lisa Cloutier 6124 E 162nd Ave, Verra Clark 16123 Krameria Ct, and Laurie Jorgensen 6103 E 161st Ave, Brighton Colorado.

I attempted to make phone contact with the complainants but I did not receive any call back from any of the complainants.

I performed a complete site inspection of the location on 4-3-2017. At the time of inspection, I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaints. All lighting on the rig were pointed down and toward the center of the location at the time of the inspection see inspections Doc#672500483 for attached photos of rig lighting. No odors were detected off the location at the time of the inspection.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

No violations of COGCC rules were observed at the time of the inspection.

Corrective Action:

Date:

Well Drilling

Rig: Rig Name: PRECISION RIG 460 Pusher/Rig Manager: _____

Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES

Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____

Multi-Well: YES	Disposal Location: WASTE MANAGEMENT			
Comment:				
Corrective Action:				Date:
Facility ID: 449165	Type: WELL	API Number: 001-09994	Status: XX	Insp. Status: DG
Facility ID: 449167	Type: WELL	API Number: 001-09996	Status: XX	Insp. Status: DG
Facility ID: 449172	Type: WELL	API Number: 001-10001	Status: XX	Insp. Status: DG

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Slope Roughening	Pass					
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Silt Fences	Pass					
Berms	Pass					
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Mulching	Pass					
Ditches	Pass			Vehicle Tracking	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
672500485	GW Ambient sound study	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116393