

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2017

Submitted Date:

04/03/2017

Document Number:

679902419

FIELD INSPECTION FORM

Loc ID 321213 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 35600
Name of Operator: GREAT WESTERN DRILLING COMPANY
Address: P O BOX 1659
City: MIDLAND State: TX Zip: 79702

Findings:

- 12 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Roberts, Sam	432-682-5241	sroberts@gwdc.com	Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206286	WELL	PR	12/06/2014	GW	011-06032	BOURNE 1	PR

General Comment:

Empty text area for general comments.

Location			
Lease Road:			
Type	Access		
comment:	Dirt trail through farm ground		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by production tank		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tank		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Stickers on chemical tanks		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Pipe from removing booster compressor needs to be picked up and removed from location		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:	Meter run on east side of location		
Corrective Action:			Date:
Type: Compressor	# 0		
Comment:	Compressor removed from location		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Type: Ancillary equipment	# 2		
Comment:	Overhead tank by meter shed and overhead storage tank w/containment		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:	Between tank and wellhead		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		38.108560,-102.844340
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210bbbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Berms need maintenance for capacity			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 206286 Type: WELL API Number: 011-06032 Status: PR Insp. Status: PR

Producing Well

Comment: [Well is SI at time of inspection](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT