

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2017

Submitted Date:

04/03/2017

Document Number:

679902425**FIELD INSPECTION FORM**

Loc ID 321221 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:                     

**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ingve, Edward	303-680-4725	ed@renegadeoilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206337	WELL	PR	12/01/2010	GW	011-06083	MCCLINTOCK 1	PR

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt road through pasture		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Sticker on production tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign mounted to meter shed		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>				corrective date
Type: Prime Mover	# 1			
Comment:	Arrow gas engine			
Corrective Action:		Date:		
Type: Pump Jack	# 1			
Comment:	Bethlehem unit. Walking beam removed from sampson post. Remove walking beam from location			
Corrective Action:		Date:		
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:		Date:		
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:		Date:		

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLS	STEEL AST		38.098210,-102.748870
Comment:					

Corrective Action:		Date:	
<b>Paint</b>			
Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			
<b>Berms</b>			
Type	Capacity	Permeability (Wall)	Maintenance
Earth	Adequate	Walls Sufficient	Adequate
Comment: Berms need maintenance if well is returned to production			
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	206337	Type:	WELL	API Number:	011-06083	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well is TA at time of inspection. Passing MIT performed on 5/27/14								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Erosion on access needs maintenance

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT