



**Inspected Facilities**

Facility ID: 261042 Type: WELL API Number: 123-20563 Status: PR Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Form 42 #401236064. Perforations are 6316'-7096', CIBP set @ 6280', MIT to maintain TA status, ICP @ 0# psi, MIRU pressure truck, pressure csg to 500# psi, 5 minute csg pressure @ 490# psi, 10 minute csg pressure @ 490# psi, 15 minute csg pressure @ 490# psi, release pressure, RDMO pressure truck, SIW.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead valve is exposed at surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401247943	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113067">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113067</a>