



Photo 1: View of the project area from the southeastern corner facing center.



Photo 2: View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing, largely with grasses such as orchardgrass (*Dactylis glomerata*), crested wheatgrass (*Agropyron cristatum*), and intermediate wheatgrass (*Thinopyron intermedium*).



Photo 3: View of the eastern portion of the project area from the southeastern edge facing northward.



Photo 4: View of musk thistles (*Carduus nutans*) within the interim reclamation area.



Photo 5: Another view of musk thistles within the interim reclamation area.



Photo 6: View of stormwater controls in the western portion of the project area appear to be functioning.