



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner facing southward. Revegetation is progressing but weedy, and largely comprised of smooth brome (*Bromus inermis*) and sand dropseed (*Sporobolus* sp.).



Photo 3: View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 4: View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 5: View of musk thistles (*Carduus nutans*) within the western portion of the project area.



Photo 6: View of erosional channel (approximately 2 feet wide and deep) forming within the western portion of the project area.