

# Inspection Photos

Location Name: DOE 1-M-25

Location Number :335097

API: 05-045-06987

Inspection Number: 674703806



Battery sign at sepearators



Facility tank and equipment.

Inspection Photos

Location Name:

API: 05-

Inspection Number:



**Well heads**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources