

## Inspection Photos

Location Name: GM 23-36

Location Number :335145

API: 05-045-14691-00

Inspection Number: 674703810



Battery sign at sepearators



Wireline unit rigging down after replacing stankding valve in well.