

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/04/2017

Submitted Date:

04/04/2017

Document Number:

674703796**FIELD INSPECTION FORM**

Loc ID 335799 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274603	WELL	TA		DSPW	045-13367	N.PARACHUTE WF09D M14 596	TA

General Comment:

Inspected FacilitiesFacility ID: 274603 Type: WELL API Number: 045-13367 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Previous test was 8/8/12 doc. #1772089

Corrective Action: _____ Date: _____

BradenHeadComment: 40 psi on braden bleed off in 4 mins to 0 psi

Corrective Action: _____ Date: _____

WorkoverComment: Witness Mechanical Integrity Test. Previous test was 8/8/12 doc. #1772089 Tested to 351 psi for 15 minutes. 5 min - 348 psi 10 min - 344 psi Final (15 min) - 344 psi. Plug set at 3130' perfs interval 3214' to 4258' Plug 84' above perfs.

Corrective Action: _____ Date: _____