

Inspection Photos

04/06/2017

Operator: Bonanza Creek Energy #8960

Location ID: 305141

Inspection Doc. Number: 682501859

Weld County, CO

NWNW Section 17 T5N R61W

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: Bonanza Creek
Location ID: 305141



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: Bonanza Creek
Location ID: 305141



Photo 2: Photo taken from the location, facing southwest. Photo shows large portions of the location where gravel and base material have not been removed and remain unvegetated. 6 foot measuring stick for reference.



Photo 3: Photo taken from the location, facing southwest. Photo shows large portions of the location where gravel and base material have not been removed and remain unvegetated. 6 foot measuring stick for reference.

Inspection Photos
Operator: Bonanza Creek
Location ID: 305141



Photo 4: Photo taken from the location. Photo shows large portions of the location where gravel and base material have not been removed and remain unvegetated. 6 foot measuring stick for reference.



Photo 5: Photo taken from the location. Photo shows large portions of the location where gravel and base material have not been removed and remain unvegetated. 6 foot measuring stick for reference.