

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/05/2017

Submitted Date:

04/10/2017

Document Number:

680101651

**FIELD INSPECTION FORM**

Loc ID 449385 Inspector Name: Colby, Lou On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449386	WELL	XX	02/28/2017		045-23434	WARE SR 533-12	CI
449387	WELL	XX	02/28/2017		045-23435	WARE SR 514-12	CI
449388	WELL	XX	02/28/2017		045-23436	WARE SR 14-12	CI
449389	WELL	XX	02/28/2017		045-23437	WARE SR 324-12	CI
449390	WELL	XX	02/28/2017		045-23438	WARE SR 34-12	CI
449391	WELL	XX	02/28/2017		045-23439	WARE SR 23-12	CI
449392	WELL	XX	02/28/2017		045-23440	WARE SR 423-12	CI
449393	WELL	XX	02/28/2017		045-23441	WARE SR 513-12	CI
449394	WELL	XX	02/28/2017		045-23442	WARE SR 523-12	CI
449395	WELL	XX	02/28/2017		045-23443	WARE SR 413-12	CI
449396	WELL	XX	02/28/2017		045-23444	WARE SR 512-12	CI
449397	WELL	XX	02/28/2017		045-23445	WARE SR 24-12	CI
449398	WELL	XX	02/28/2017		045-23446	WARE SR 524-12	CI
449399	WELL	XX	02/28/2017		045-23447	WARE SR 522-12	CI
449400	WELL	XX	02/28/2017		045-23448	WARE SR 313-12	CI
449401	WELL	XX	02/28/2017		045-23449	WARE SR 412-12	CI
449402	WELL	XX	02/28/2017		045-23450	WARE SR 424-12	CI
449403	WELL	XX	02/28/2017		045-23451	WARE SR 334-12	CI
449404	WELL	XX	02/28/2017		045-23452	WARE SR 323-12	CI
449405	WELL	XX	02/28/2017		045-23453	WARE SR 314-12	CI
449406	WELL	XX	02/28/2017		045-23454	WARE SR 13-12	CI
449407	WELL	XX	02/28/2017		045-23455	WARE SR 414-12	CI
449408	WELL	XX	02/28/2017		045-23456	WARE SR 433-12	CI
449409	WELL	XX	02/28/2017		045-23457	WARE SR 534-12	CI

**General Comment:**

This is a Construction and Stormwater Inspection; New Pad Construction. Form 42 (Notice of Construction) has been Filed for this Location; Start Date as 3/13/2017. Conditions at time of Inspection were light overcast, at 53 degrees F.

**Location Construction**

Location ID: 449385 CDP: \_\_\_\_\_

Comment: Pad construction is well progressed. Access Road entry was in process of being cut down, roughing up and congesting entry. Four pieces of equipment were working at time of Inspection.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment: This location is included in a Wildlife Mitigation Plan. The facility lies within the external buffer zone of the Beaver Creek 317B area. Therefore by COGCC rule, the 317B buffer zone classifies the facility as being in a sensitive area.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
SLOPE ROUGHENING	Yes		

Comments: Erosion BMPs: \_\_\_\_\_  
Other BMPs: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

DITCHES	Yes		

Comments: Erosion BMPs: Ditches have been installed around perimeter of Location  
Other BMPs: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

## Inspected Facilities

Facility ID: <u>449386</u>	Type: <u>WELL</u>	API Number: <u>045-23434</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449387</u>	Type: <u>WELL</u>	API Number: <u>045-23435</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449388</u>	Type: <u>WELL</u>	API Number: <u>045-23436</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449389</u>	Type: <u>WELL</u>	API Number: <u>045-23437</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449390</u>	Type: <u>WELL</u>	API Number: <u>045-23438</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449391</u>	Type: <u>WELL</u>	API Number: <u>045-23439</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449392</u>	Type: <u>WELL</u>	API Number: <u>045-23440</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449393</u>	Type: <u>WELL</u>	API Number: <u>045-23441</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449394</u>	Type: <u>WELL</u>	API Number: <u>045-23442</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449395</u>	Type: <u>WELL</u>	API Number: <u>045-23443</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449396</u>	Type: <u>WELL</u>	API Number: <u>045-23444</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449397</u>	Type: <u>WELL</u>	API Number: <u>045-23445</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449398</u>	Type: <u>WELL</u>	API Number: <u>045-23446</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449399</u>	Type: <u>WELL</u>	API Number: <u>045-23447</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449400</u>	Type: <u>WELL</u>	API Number: <u>045-23448</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449401</u>	Type: <u>WELL</u>	API Number: <u>045-23449</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449402</u>	Type: <u>WELL</u>	API Number: <u>045-23450</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449403</u>	Type: <u>WELL</u>	API Number: <u>045-23451</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449404</u>	Type: <u>WELL</u>	API Number: <u>045-23452</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

Facility ID: 449405	Type: WELL	API Number: 045-23453	Status: XX	Insp. Status: CI
Facility ID: 449406	Type: WELL	API Number: 045-23454	Status: XX	Insp. Status: CI
Facility ID: 449407	Type: WELL	API Number: 045-23455	Status: XX	Insp. Status: CI
Facility ID: 449408	Type: WELL	API Number: 045-23456	Status: XX	Insp. Status: CI
Facility ID: 449409	Type: WELL	API Number: 045-23457	Status: XX	Insp. Status: CI

**COGCC Comments**

Comment	User	Date
Follow up inspection(s) will proceed while construction of location is IN-PROCESS. Refer to Photos attached for more detail. Please note that Photo date stamp is one day off actual Date.	colbyl	04/10/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680101652	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4120798">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4120798</a>