

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2017

Submitted Date:

04/11/2017

Document Number:

684903462**FIELD INSPECTION FORM**

Loc ID 448269 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager
Adamczyk, Megan		megan.adamczyk@state.co.us	
Powell, Harold	(918)-774-3120	hpowell@petrosharecorp.com	Field Op Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448268	WELL	DG	04/10/2017		001-09975	Shook 3-10-1NCH	DG

General Comment:

Inspected Facilities

Facility ID: 448268 Type: WELL API Number: 001-09975 Status: DG Insp. Status: DG

Complaint

Comment: Complaint #: 200441289, 200441288

Field Inspector Assigned: C Pesicka

Nature of complaint: Noise and Lighting

If Sound GPS Coordinates of Survey Location: 39.99236, -104.87099

Inspection Observations:

OGCC was on location at 9:00pm on 4/11/17. All lighting on location was directed downward and inward. None of complainant structures are within 1000' of location.

Location is compliant with rule 803.

Location on 4/11/17 is drilling surface hole. Winds were calm, ambient temperature was 45° F, sound survey was run 350' from east of location from 9:00am to 10:00am. Photo of sound survey location attached. The sound survey resulted in an LeqA of 62.2 dB, which is compliance with rule 802.

18A doc# 200441295, 200441297

Corrective Action:

Date:

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____

Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____

Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____

Multi-Well: _____ Disposal Location: _____

Comment: Drilling surface

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
684903463	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4121157
684903464	Sound study report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4121158