

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2017

Submitted Date:

04/11/2017

Document Number:

666803096

### FIELD INSPECTION FORM

Loc ID 323908	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: PO BOX 370 City: PARACHUTE State: CO Zip: 81635				<b>Findings:</b> 18 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

<b>Contact Information:</b>			
Contact Name , Inspections	Phone	Email COGCCInspectionReports@terraep.com	Comment Field Inspections

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211161	WELL	PR	01/17/1995	GW	045-06920	JUHAN RMV 22-35	PR
413211	WELL	PR	12/01/2010	GW	045-18742	SAVAGE RWF 442-35	PR
413217	WELL	PR	12/14/2015	GW	045-18745	SAVAGE RWF 41-35	PR
413220	WELL	PR	10/31/2010	OG	045-18747	SAVAGE RWF 32-35	PR
413223	WELL	PR	03/16/2017	OG	045-18749	RWF 331-35	PR
413224	WELL	PR	08/31/2010	GW	045-18750	SAVAGE RWF 42-35	PR
413227	WELL	PR	10/31/2010	OG	045-18752	Savage RWF 432-35	PR
413230	WELL	PR	06/30/2010	GW	045-18753	SAVAGE RWF 341-35	PR
413231	WELL	PR	10/29/2010	OG	045-18755	Savage RMV 147-35	PR
413232	WELL	PR	08/31/2010	GW	045-18756	SAVAGE RWF 342-35	PR
413234	WELL	PR	08/31/2010	GW	045-18758	SAVAGE RWF 541-35	PR
413237	WELL	PR	10/31/2010	OG	045-18760	Savage RWF 532-35	PR
413239	WELL	PR	06/30/2010	GW	045-18762	SAVAGE RWF 31-35	PR
413241	WELL	PR	12/01/2010	GW	045-18764	SAVAGE RWF 542-35	PR
413248	WELL	PR	08/31/2010	GW	045-18769	SAVAGE RWF 332-35	PR
413250	WELL	PR	08/31/2010	GW	045-18770	SAVAGE RWF 441-35	PR

<b>General Comment:</b>
-------------------------

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Horizontal Heated Separator	# 16				
Ancillary equipment	# 3	Chemical units at wellhead			
Vertical Separator	# 2				
Plunger Lift	# 16				

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		39.486583,-107.852839
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities										
Facility ID:	211161	Type:	WELL	API Number:	045-06920	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	413211	Type:	WELL	API Number:	045-18742	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	413217	Type:	WELL	API Number:	045-18745	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	413220	Type:	WELL	API Number:	045-18747	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	413223	Type:	WELL	API Number:	045-18749	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	413224	Type:	WELL	API Number:	045-18750	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	413227	Type:	WELL	API Number:	045-18752	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Plunger lift									
Corrective Action:							Date:			
Facility ID:	413230	Type:	WELL	API Number:	045-18753	Status:	PR	Insp. Status:	PR	
<b>Producing Well</b>										
Comment:	Plunger lift									
Corrective Action:							Date:			

Facility ID: 413231	Type: WELL	API Number: 045-18755	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:			Date:	
Facility ID: 413232	Type: WELL	API Number: 045-18756	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:			Date:	
Facility ID: 413234	Type: WELL	API Number: 045-18758	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:			Date:	
Facility ID: 413237	Type: WELL	API Number: 045-18760	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:			Date:	
Facility ID: 413239	Type: WELL	API Number: 045-18762	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:			Date:	
Facility ID: 413241	Type: WELL	API Number: 045-18764	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:			Date:	
Facility ID: 413248	Type: WELL	API Number: 045-18769	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:			Date:	
Facility ID: 413250	Type: WELL	API Number: 045-18770	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:			Date:	



**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Pass					
Ditches	Pass					
Gravel	Pass					
		Gravel	Pass			
Seeding	Pass					
		Ditches	Pass			
Retention Ponds	Pass					
		Culverts	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	422631	2213249	