

Inspection Photos

04/11/2017

Operator: Noble Energy #100322

Location ID: 305414

Inspection Doc. Number: 682501867

Weld County, CO

NENE Section 35 T8N R59W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: Noble Energy
Location ID: 305414



Photo 1: Photo taken from the northwest corner of the location, facing east. Photo shows reclamation in areas of the location is progressing.



Photo 2: Photo taken from the northwest corner of the location, facing southeast. Photo shows reclamation in areas of the location is progressing.

Inspection Photos
Operator: Noble Energy
Location ID: 305414



Photo 3: Photo taken from the northwest corner of the location, facing south. Photo shows reclamation in areas of the location is progressing.



Photo 4: Photo taken from location. Photo shows straw wattles on the location have not been maintained and are in disrepair. Wattles in current condition is debris and needs to be either repaired or removed.

Inspection Photos
Operator: Noble Energy
Location ID: 305414



Photo 5: Photo taken from location. Photo shows vegetation over areas of the reclamation that are progressing.



Photo 6: Photo taken from the south end of the location, facing southwest. Photo shows areas of the location that remain unvegetated with little desirable perennial growth evident. These areas will require additional reclamation work.

Inspection Photos
Operator: Noble Energy
Location ID: 305414



Photo 7: Photo taken from the south end of the location, facing south. Photo shows areas of the location that remain unvegetated with little desirable perennial growth evident. These areas will require additional reclamation work.



Photo 8: Photo taken from the southwest corner of the location, facing southwest. Photo shows gate at access road is not in proper functioning condition. Livestock presence within reclamation area evident. This is the likely point of access for livestock into the reclamation area. Advise maintenance.

Inspection Photos
Operator: Noble Energy
Location ID: 305414



Photo 9: Photo taken from the southwest end of the location, facing northwest. Photo shows the reclamation on the access road is in-process.



Photo 10: Photo taken from the south end of the location, facing west. Photo shows areas of the location that remain unvegetated with little desirable perennial growth evident. These areas will require additional reclamation work.

Inspection Photos
Operator: Noble Energy
Location ID: 305414



Photo 11: Photo taken from access road, east of the location. Photo shows cattle guard that has not been removed.



Photo 12: Photo taken from access road, east of the location. Photo shows cattle guard that has not been removed. Note label on cattle guard says "Noble Energy Inc."