


Photo#1:

Entry into Location; view to South

\*



Photo#2:

Tracked disturbed area to SW of Cattle Guard; note population & new growth of Curly Dock in this area



April 2, 2017

### Photo#3:

View over Location from SW Corner to NE.



April 2, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: PA Deep Seam API#077-08579

Photo#4:

Photo#5:

Old & New Growth Thistle as well as Houndstongue (B List Noxious Weeds) on Location.



April 2, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: PA Deep Seam API#077-08579

Photo#6:

Photo#7:

Wattles are installed on steep slope at East Side of Location.



April 2, 2017

## Photo#8:

Aerial View of Subject Well & Access Rd. Well 077-08563 did appear to have a pre existing Ranch Rd to it's site.



April 2, 2017