

**Inspection Photos**  
**Location Name: Colorado Federal 1**  
**API: 05-123-10203**



**Photo from prior inspection for comparison purposes**



**Photo 1: Weeds controlled, bird protector installed**

**Inspection Photos**  
**Location Name: Colorado Federal 1**  
**API: 05-123-10203**



**Photo from prior inspection for comparison purposes**



**Photo 2: Unused equipment removed**



**Inspection Photos**  
**Location Name: Colorado Federal 1**  
**API: 05-123-10203**



**Photo from prior inspection for comparison purposes**



**Photo 3: Weeds around wellhead controlled; stained soil removed or remediated**

**Inspection Photos**  
**Location Name: Colorado Federal 1**  
**API: 05-123-10203**



**Photo from prior inspection for comparison purposes**



**Photo 4: Stained soil removed**



**Inspection Photos**  
**Location Name: Colorado Federal 1**  
**API: 05-123-10203**



**Photo from prior inspection for comparison purposes**



**Photo 5: Tanks labeled, weeds controlled**

**Inspection Photos**  
**Location Name: Colorado Federal 1**  
**API: 05-123-10203**



**Photo from prior inspection for comparison purposes**



**Photo 6: Stained soil removed or remediated**



**Inspection Photos**  
**Location Name: Colorado Federal 1**  
**API: 05-123-10203**



**Photo from prior inspection for comparison purposes**



**Photo 7: Stained soil removed or remediated**

**Inspection Photos**  
**Location Name: Colorado Federal 1**  
**API: 05-123-10203**



**Photo from prior inspection for comparison purposes**



**Photo 8: Stained soil removed or remediated**



**Inspection Photos**  
**Location Name: Colorado Federal 1**  
**API: 05-123-10203**



**Photo 9: Stained soil at base of tank**



**Photo 10: No emergency number on battery sign**