

Inspection Photos  
Location Name: Jones 1-11  
API: 05-107-06093



**Photo 1. View at entrance to location area with wellhead, facing east. Unlabeled propane tanks visible in foreground.**

Inspection Photos  
Location Name: Jones 1-11  
API: 05-107-06093



**Photo 2. Stained soil at tank base of crude tank near wellhead.**



**Photo 3. View of battery portion of location facing northwest.**