

Inspection Photos  
Location Name: Federal Coalmont 23-12R  
API: 05-057-06492



**Photo 1. View of location at entrance facing northwest.**



**Photo 2. Missing tank labels.**