

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2017

Submitted Date:

04/11/2017

Document Number:

684903462**FIELD INSPECTION FORM**Loc ID 448269 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Powell, Harold	(918)-774-3120	hpowell@petrosharecorp.com	Field Op Manager
Adamczyk, Megan		megan.adamczyk@state.co.us	
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448268	WELL	DG	04/10/2017		001-09975	Shook 3-10-1NCH	DG

**General Comment:**

**Inspected Facilities**

Facility ID: 448268 Type: WELL API Number: 001-09975 Status: DG Insp. Status: DG

**Complaint**

Comment: Complaint #: 200441289, 200441288

Field Inspector Assigned: C Pesicka

Nature of complaint: Noise and Lighting

If Sound GPS Coordinates of Survey Location: 39.99236, -104.87099

Inspection Observations:

OGCC was on location at 9:00pm on 4/11/17. All lighting on location was directed downward and inward. None of complainant structures are within 1000' of location.

Location is compliant with rule 803.

Location on 4/11/17 is drilling surface hole. Winds were calm, ambient temperature was 45° F, sound survey was run 350' from east of location from 9:00am to 10:00am. Photo of sound survey location attached. The sound survey resulted in an LeqA of 62.2 dB, which is compliance with rule 802.

18A doc# 200441295, 200441297

Corrective Action:

Date:

**Well Drilling**

Rig: Rig Name: Pusher/Rig Manager:

Permit Posted: Access Sign:

**Well Control Equipment:**

Pipe Ram: Blind Ram: Hydril Type:

Pressure Test BOP: Test Pressure PSI: Safety Plan:

**Drill Fluids****Management:**

Lined Pit: Unlined Pit: Closed Loop: Semi-Closed Loop:

Multi-Well: Disposal Location:

Comment: Drilling surface

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
401256102	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4121162">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4121162</a>
684903463	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4121157">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4121157</a>
684903464	Sound study report	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4121158">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4121158</a>