

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/11/2017

Submitted Date:

04/11/2017

Document Number:

687300015**FIELD INSPECTION FORM**

Loc ID 305447	Inspector Name: Gomez, Jason	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10633</u> Name of Operator: <u>CRESTONE PEAK RESOURCES OPERATING LLC</u> Address: <u>1801 CALIFORNIA STREET #2500</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: <u>4</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		megan.adamczk@state.co.us	
		cogcc.inspections@crestonepr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434333	WELL	DG	10/17/2016	LO	123-38104	Woolley Sosa 2A-7H-E168	DG
434334	WELL	DG	11/03/2016	LO	123-38105	Woolley Becky 2F-7H-E168	DG
434335	WELL	DG	10/23/2016	LO	123-38106	Woolley Sosa 2D-7H-E168	DG
434336	WELL	DG	11/01/2016	LO	123-38107	Woolley Becky 2D-7H-E168	DG
434337	WELL	DG	10/18/2016	LO	123-38108	Woolley Sosa 2B-7H-E168	DG
434338	WELL	DG	10/30/2016	LO	123-38109	Woolley Becky 2B-7H-E168	DG
434339	WELL	DG	10/24/2016	LO	123-38110	Woolley Sosa 2E-7H-E168	DG
434340	WELL	DG	10/29/2016	LO	123-38111	Woolley Becky 2A-7H-E168	DG
434341	WELL	DG	11/02/2016	LO	123-38112	Woolley Becky 2E-7H-E168	DG
434342	WELL	DG	10/26/2016	LO	123-38113	Woolley Sosa 2F-7H-E168	DG
434343	WELL	DG	11/05/2016	LO	123-38114	Woolley Becky 2H-7H-E168	DG
436731	WELL	DG	10/31/2016	LO	123-39241	Woolley Becky 2C-7H-E168	DG
436733	WELL	DG	11/04/2016	LO	123-39242	Woolley Becky 2G-7H-E168	DG
436738	WELL	DG	10/19/2016	LO	123-39245	Woolley Sosa 2C-7H-E168	DG
436739	WELL	DG	10/30/2016	LO	123-39246	Woolley Sosa 2G-7H-E168	DG

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	#		corrective date
Comment:	APPROX 32' SOUND WALLS		
Corrective Action:		Date:	
Type: Ancillary equipment	#		
Comment:	APPROX 20' SOUND WALLS IN LOCATION FOR ADDITIONAL SOUND MITIGATION		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Field Flare	
Comment:	NOT IN USE AT TIME OF INSPECTION	
Corrective Action:		Date:

Inspected Facilities

Facility ID: 434333 Type: WELL API Number: 123-38104 Status: DG Insp. Status: DG

Complaint

Comment: Complaint #: 200441290 / 200441292

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 4-10-2017 Time 1220 Hrs

Contacted by Inspector:

Date: 4-10-2017 Time 1241 Hrs

Well Number#: Location #: 305447

Inspection Document #: 687300015

Complainant: Gary Gianetti Eileen Rojas Phone: 860-933-0524

Address: 1379 Padfield Pl, Erie CO 80516

Nature of complaint: Noise

Field Inspector Actions:

On 4-10-2017, I was contacted by James Precup NE supervisor of the COGCC in reference to a noise complaint at the residence of the complainants Sally Towner 1369 Washburn St, and Garry Gianetti 1379 Padfield PL in Erie Colorado.

I performed a complete site inspection of the location on 4-10-2017. At the time of inspection, I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaints. I also reviewed Environmental Noise Control Inc. continuous sound study information.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

No violations of COGCC rules were observed at the time of the inspection.

Corrective Action:

Date:

Well Drilling

Rig: Rig Name: ENSIGN RIG 140 Pusher/Rig Manager: RICK WADLEY

Permit Posted: Yes

Access Sign: Yes

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES

Pressure Test BOP: Pass

Test Pressure PSI:

Safety Plan:

YES

Drill Fluids**Management:**

Lined Pit:

Unlined Pit:

Closed Loop: YES

Semi-Closed Loop:

Multi-Well: YES

Disposal Location:

Comment:

Corrective Action:

Date:

Facility ID: 434334 Type: WELL API Number: 123-38105 Status: DG Insp. Status: DG

Facility ID:	<u>434335</u>	Type:	<u>WELL</u>	API Number:	<u>123-38106</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>
Facility ID:	<u>434336</u>	Type:	<u>WELL</u>	API Number:	<u>123-38107</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>
Facility ID:	<u>434337</u>	Type:	<u>WELL</u>	API Number:	<u>123-38108</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>
Facility ID:	<u>434338</u>	Type:	<u>WELL</u>	API Number:	<u>123-38109</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>
Facility ID:	<u>434339</u>	Type:	<u>WELL</u>	API Number:	<u>123-38110</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>
Facility ID:	<u>434340</u>	Type:	<u>WELL</u>	API Number:	<u>123-38111</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>
Facility ID:	<u>434341</u>	Type:	<u>WELL</u>	API Number:	<u>123-38112</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>
Facility ID:	<u>434342</u>	Type:	<u>WELL</u>	API Number:	<u>123-38113</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>
Facility ID:	<u>434343</u>	Type:	<u>WELL</u>	API Number:	<u>123-38114</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>
Facility ID:	<u>436731</u>	Type:	<u>WELL</u>	API Number:	<u>123-39241</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>
Facility ID:	<u>436733</u>	Type:	<u>WELL</u>	API Number:	<u>123-39242</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>
Facility ID:	<u>436738</u>	Type:	<u>WELL</u>	API Number:	<u>123-39245</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>
Facility ID:	<u>436739</u>	Type:	<u>WELL</u>	API Number:	<u>123-39246</u>	Status:	<u>DG</u>	Insp. Status:	<u>DG</u>

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	NOT IN USE AT TIME OF INSPECTION
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Waddles	Pass					
Ditches	Pass			Material Handling And Spill Prevention	Pass	
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Gravel	Pass			Vehicle Tracking	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401256892	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4121819