Inspector Name: Carlile, Craig

FORM INSP

Rev X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

FIELD INSPECTION FORM



**Facility Name** 

RUTH ELIZABETH HICKS

Inspection Date: 04/12/2017 Submitted Date: 04/12/2017

Document Number: 674005035

Insp Status

PΑ

						<u> </u>	
Loc ID	Inspector Name:		nspection			s Summary:	
317989 Carlile, Craig 2A Doc Num			Doc Num: _		THIS IS A FOLLOW UP INSPECTION		
Operator Information:						FOLLOW UP INSPECTION REQUIRED	
OGCC Operator Number: 47120					NO FOLLOW UP INSPECTION REQUIRED		
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP					Findings:		
Address: P O BOX 173779					2	Number of Comments	
_					0	Number of Corrective Actions	
City:	DENVER St	ate: CO	Zip:8	0217-	Cc	prrective Action Response Requested	
Contact Information:							
Contact Name		Phone	Email			Comment	
, Inspection	ns		COGCCinspo.com	pections@Ana	dark	All Inspections	
Inspected Facilities:							

Well Class

OW

API Num

123-08117

_	_	_	
Gen	eral	Comm	ent.

Type

WELL

Status

PR

Status Date

05/17/2003

Facility ID

240329

Inspector Name: Carlile, Craig

				Inspected	d Facilities				
Facility ID:	240329	Type: _	WELL	API Number:	123-08117	Status: _	PR	Insp. Status:	PA

COGCC Comments				
Comment	User	Date		
Well has been plugged and abandoned. Form 6 number: 40122615 Awaiting reclamation.	carlilec	04/12/2017		

## **Attached Documents**

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
	'	
401257464	INSPECTION	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4122632
	SUBMITTED	