

Photo#1:

Overview of Location to South



April 17, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Crystal Creek API#045-06476

Photo#2:

Culverts Housing Lines/Valves are still open / uncovered



April 17, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Crystal Creek API#045-06476

Photo#3:

Large Pit Located North of Well.



April 17, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Crystal Creek API#045-06476

Photo#4:

Facilities /Equipment on Location. .

Photo#5:



April 17,2017