



Photo 1: View of the project area from the well pad entrance facing center.



Photo 2: View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is largely comprised of grasses such as dropseed (*Sporobolus* sp.). Much of the revegetation is comprised of annual weeds such as cheatgrass (*Bromus tectorum*) and stork's bill (*Erodium cicutarium*). Northeastern cut-slope is too steep to support vegetation.



Photo 3: View of the western portion of the project area from the northwestern edge facing southward.



Photo 4: Birdseye view of typical vegetation on the northern slope, which is largely annual weeds.