

Inspection Photos

04/13/2017

Operator: Red Mountain Resources #10374

Location ID: 312132

Inspection Doc. Number: 682501885

Logan County, CO

NWSW Section 21 T6N R54W

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: Red Mountain
Location ID: 312132



Photo 1: Photo taken from the west end of the pump unit. Photo of sign at well.

Inspection Photos
Operator: Red Mountain
Location ID: 312132



Photo 4: Photo taken from the west end of the pumping unit. Photo shows location area and pumping unit. Adjacent reference area in poor condition, there appears to show heavy grazing pressure, this is likely due to a combination of livestock and dense prairie dog populations.