

Inspection Photos
Location Name: Welch AC 21-13
API: 05-123-29705



Photo from prior inspection of location



Photo from prior inspection of wellhead

Inspection Photos
Location Name: Welch AC 21-13
API: 05-123-29705



Photo from prior inspection for comparison purposes



Photo 1: Stained soil removed from wellhead