

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2017

Submitted Date:

04/18/2017

Document Number:

680101660**FIELD INSPECTION FORM**

Loc ID 448427	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 10 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
------------------	-------------------------------	---	-------------------	---

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
Janicek, Jake		jjanicek@caerusoilandgas.com	EH&S
		mmckee@caerusoilandgas.com	
Reed, Haddock.	(720) 880-6369	rhaddock@caerusoilandgas.com	Sr. Regulatory Specialist
		garrett@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448425	WELL	XX	11/28/2016		045-23372	Puckett 11A-26 697	CI
448426	WELL	XX	11/28/2016		045-23373	Puckett 13D-23 697	CI
448428	WELL	XX	11/28/2016		045-23374	Puckett 24C-23 697	CI
448429	WELL	XX	11/28/2016		045-23375	Puckett 13C-23 697	CI
448430	WELL	XX	11/28/2016		045-23376	Puckett 15D-23 697	CI
448431	WELL	XX	11/28/2016		045-23377	Puckett 33C-23 697	CI
448432	WELL	XX	11/28/2016		045-23378	Puckett 15C-23 697	CI
448433	WELL	XX	11/28/2016		045-23379	Puckett 24D-23 697	CI
448434	WELL	XX	11/28/2016		045-23380	Puckett 15B-23 697	CI
448435	WELL	XX	11/28/2016		045-23381	Puckett 33D-23 697	CI
448436	WELL	XX	11/28/2016		045-23382	Puckett 24B-23 697	CI
448437	WELL	XX	11/28/2016		045-23383	Puckett 14B-23 697	CI
448438	WELL	XX	11/28/2016		045-23384	Puckett 34B-23 697	CI
448439	WELL	XX	11/28/2016		045-23385	Puckett 14C-23 697	CI
448440	WELL	XX	11/28/2016		045-23386	Puckett 11C-26 697	CI
448441	WELL	XX	11/28/2016		045-23387	Puckett 23D-23 697	CI
448442	WELL	XX	11/28/2016		045-23388	Puckett 24A-23 697	CI
448443	WELL	XX	11/28/2016		045-23389	Puckett 15A-23 697	CI
448444	WELL	XX	11/28/2016		045-23390	Puckett 14D-23 697	CI

448445	WELL	XX	11/28/2016		045-23391	Puckett 14A-23 697	CI
448446	WELL	XX	11/28/2016		045-23392	Puckett 25A-23 697	CI
448447	WELL	XX	11/28/2016		045-23393	Puckett 34A-23 697	CI
448448	WELL	XX	11/28/2016		045-23394	Puckett 25B-23 697	CI
448449	WELL	XX	11/28/2016		045-23395	Puckett 11B-26 697	CI

General Comment:

This is a Construction and Stormwater Inspection. Form 42 : NOTICE OF CONSTRUCTION: was Filed for this Site, Start Date 4/10/17. Conditions at time of Inspection were Scattered Partly Cloudy skies, light breeze from the SE at 55 degrees F. Elevation at Site is 8,437 ft.

Location Construction

Location ID: 448427 CDP: _____

Comment: Access Road is in place, construction on Pad was ongoing; two Dozers working at time of Inspection. Caerus EHS and Contractor Construction Foreman were on Site.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: Location is within SWH Greater Sage Grouse Area.

Corrective Action: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
WADDLES	Yes		

Comments: Erosion BMPs: Wattles have been installed around Location Perimeters

Other BMPs: _____

Corrective Action: _____ Date: _____

DITCHES	Yes		
---------	-----	--	--

Comments: Erosion BMPs: Ditches & Culvert have been installed along Access Rd, and ditches at points along Location.

Other BMPs: _____

Corrective Action: _____ Date: _____

RETENTION PONDS	Yes		
-----------------	-----	--	--

Comments: Erosion BMPs: Roughened in Retention Ponds are in place

Other BMPs: _____

Corrective Action: _____ Date: _____

Comment: Sufficient SW BMPs are in place at this time. One Wattle was dislodged (Wildlife interaction) from seat at Southern perimeter of Location; Operator was made aware.

Corrective Action: _____ Date: _____

On Site Inspection (305):**Surface Owner Contact Information:**

Name: _____ Address: _____

Inspector Name: Colby, Lou

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities				
Facility ID: <u>448425</u>	Type: <u>WELL</u>	API Number: <u>045-23372</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448426</u>	Type: <u>WELL</u>	API Number: <u>045-23373</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448428</u>	Type: <u>WELL</u>	API Number: <u>045-23374</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448429</u>	Type: <u>WELL</u>	API Number: <u>045-23375</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448430</u>	Type: <u>WELL</u>	API Number: <u>045-23376</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448431</u>	Type: <u>WELL</u>	API Number: <u>045-23377</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448432</u>	Type: <u>WELL</u>	API Number: <u>045-23378</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448433</u>	Type: <u>WELL</u>	API Number: <u>045-23379</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448434</u>	Type: <u>WELL</u>	API Number: <u>045-23380</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448435</u>	Type: <u>WELL</u>	API Number: <u>045-23381</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448436</u>	Type: <u>WELL</u>	API Number: <u>045-23382</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448437</u>	Type: <u>WELL</u>	API Number: <u>045-23383</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448438</u>	Type: <u>WELL</u>	API Number: <u>045-23384</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448439</u>	Type: <u>WELL</u>	API Number: <u>045-23385</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448440</u>	Type: <u>WELL</u>	API Number: <u>045-23386</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448441</u>	Type: <u>WELL</u>	API Number: <u>045-23387</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448442</u>	Type: <u>WELL</u>	API Number: <u>045-23388</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448443</u>	Type: <u>WELL</u>	API Number: <u>045-23389</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448444</u>	Type: <u>WELL</u>	API Number: <u>045-23390</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

Inspector Name: Colby, Lou

Facility ID: 448445	Type: WELL	API Number: 045-23391	Status: XX	Insp. Status: CI
Facility ID: 448446	Type: WELL	API Number: 045-23392	Status: XX	Insp. Status: CI
Facility ID: 448447	Type: WELL	API Number: 045-23393	Status: XX	Insp. Status: CI
Facility ID: 448448	Type: WELL	API Number: 045-23394	Status: XX	Insp. Status: CI
Facility ID: 448449	Type: WELL	API Number: 045-23395	Status: XX	Insp. Status: CI

COGCC Comments

Comment	User	Date
Follow up inspection(s) will proceed while construction of location is IN-PROCESS. Refer to Photos attached for more detail.	colbyl	04/18/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680101669	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4128599