

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/12/2017

Submitted Date:

04/14/2017

Document Number:

681902079**FIELD INSPECTION FORM**
 Loc ID 448269 Inspector Name: HELGELAND, GARY On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448263	WELL	XX	11/04/2016		001-09970	Shook 3-10-1NBH	XX
448264	WELL	XX	11/04/2016		001-09971	Shook 3-10-2NBH	XX
448268	WELL	DG	04/10/2017		001-09975	Shook 3-10-1NCH	DG
448272	WELL	XX	11/04/2016		001-09978	Shook 3-10-1NAH	XX

General Comment:

Inspected Facilities

Facility ID: 448263 Type: WELL API Number: 001-09970 Status: XX Insp. Status: XX

Well Drilling

Rig: Rig Name: Star 185K Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: Land farm.

Comment: Surface casing drilled and set.

Corrective Action: _____ Date: _____

BradenHead

Comment: NO BRADENHEAD.

Corrective Action: _____ Date: _____

Facility ID: 448264 Type: WELL API Number: 001-09971 Status: XX Insp. Status: XX

Well Drilling

Rig: Rig Name: Star 185K Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: Land farm.

Comment: Surface casing drilled and set.

Corrective Action: _____ Date: _____

BradenHead

Comment: NO BRADENHEAD.

Corrective Action: _____ Date: _____

Facility ID: 448268 Type: WELL API Number: 001-09975 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Star 185K Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

**Drill Fluids
Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____

Multi-Well: _____ Disposal Location: Land farm.

Comment: Surface casing drilled and set.

Corrective Action: _____ Date: _____

BradenHeadComment: NO BRADENHEAD.

Corrective Action: _____ Date: _____

Facility ID: 448272 Type: WELL API Number: 001-09978 Status: XX Insp. Status: XX

Well Drilling**Rig:** Rig Name: Star 185K Pusher/Rig Manager: _____

Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____

Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

**Drill Fluids
Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____

Multi-Well: _____ Disposal Location: Land farm.

Comment: Surface casing drilled and set.

Corrective Action: _____ Date: _____

BradenHeadComment: NO BRADENHEAD.

Corrective Action: _____ Date: _____

Environmental**Spill/Remediation:**Comment: Corrective
Action: Date: Emission Control Burner (ECB): NOComment: Pilot: Wildlife Protection Devices (fired vessels): **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401259576	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4124244
681902080	Rig	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4124231