

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/20/2017

Submitted Date:

04/20/2017

Document Number:

681902096**FIELD INSPECTION FORM**
 Loc ID 330811 Inspector Name: HELGELAND, GARY On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448221	WELL	XX	10/31/2016		123-43807	BABCOCK 13E-33HZ	XX
448222	WELL	XX	10/31/2016		123-43808	BABCOCK 19N-33HZ	XX
448223	WELL	XX	10/31/2016		123-43809	BABCOCK 33C-33HZ	XX
448224	WELL	XX	10/31/2016		123-43810	BABCOCK 12N-33HZ	XX
448225	WELL	XX	10/31/2016		123-43811	BABCOCK 32N-33HZ	XX

**General Comment:**

**Inspected Facilities**

Facility ID: 448221 Type: WELL API Number: 123-43807 Status: XX Insp. Status: XX

**Well Drilling**

**Rig:** Rig Name: White Mountain 252 Pusher/Rig Manager: Lane Fullenwider  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: Land farm.

**Comment:** Surface casing drilled.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

**Comment:** NO BRADENHEAD.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 448222 Type: WELL API Number: 123-43808 Status: XX Insp. Status: XX

**Well Drilling**

**Rig:** Rig Name: White Mountain 252 Pusher/Rig Manager: Lane Fullenwider  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: Land farm

**Comment:** Drilling surface casing.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

**Comment:** NO BRADENHEAD.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 448223 Type: WELL API Number: 123-43809 Status: XX Insp. Status: XX

**Well Drilling**

**Rig:** Rig Name: White Mountain 252 Pusher/Rig Manager: Lane Fullenwider  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: Land farm.

Comment: Surface casing drilled.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: NO BRADENHEAD.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 448224 Type: WELL API Number: 123-43810 Status: XX Insp. Status: XX

**Well Drilling**

Rig: Rig Name: White Mountain 252 Pusher/Rig Manager: Lane Fullenwider  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: Land farm.

Comment: Surface casing drilled.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: NO BRADENHEAD.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 448225 Type: WELL API Number: 123-43811 Status: XX Insp. Status: XX

**Well Drilling**

Rig: Rig Name: White Mountain 252 Pusher/Rig Manager: Lane Fullenwider  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids  
Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: Land farm.

Comment: Surface casing drilled.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:

Date: