



Photo 1: View of the project area from the northeastern corner facing center.



Photo 2: View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is largely comprised of western wheatgrass (*Pascopyrum smithii*), dropseed (*Sporobolus* sp.), and weedy kochia (*Kochia scoparia*) along the edges of the working area.



Photo 3: View of the eastern portion of the project area from the northeastern corner facing southward. Kochia and musk thistles have been mowed.



Photo 4: View of stormwater controls in the southwestern portion of the project area.