



**Photo 1:** View of the project area from the northwestern corner facing center.



**Photo 2:** View of the northeastern portion of the project area from the northwestern corner facing southeastward. Revegetation is largely comprised of crested wheatgrass (*Agropyron cristatum*), western wheatgrass (*Pascopyrum smithii*), and blue grama (*Bouteloua gracilis*).



**Photo 3: View of the western portion of the project area from the northwestern corner facing southwestward.**



**Photo 4: View of erosion and failed stormwater controls within the eastern portion of the project area.**



**Photo 5: View of erosional channel approximately 2 feet wide and 1.5 feet deep within the eastern portion of the project area.**