



**Photo 1: View of the project area from the southern corner facing center.**



**Photo 2: View of the eastern portion of the project area from the southern corner facing northward. Revegetation is largely comprised of western wheatgrass (*Pascopyrum smithii*).**



**Photo 3: View of the southern portion of the project area from the southern corner facing westward.**



**Photo 4: View of vegetated swale in the northeastern portion of the project area that appears stabilized at this time.**



**Photo 5: View of wattle debris that should be removed.**