

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/18/2017

Submitted Date:

04/22/2017

Document Number:

673715271**FIELD INSPECTION FORM**
 Loc ID 429843 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10399Name of Operator: NIGHTHAWK PRODUCTION LLCAddress: 1805 SHEA CENTER DR #290City: HIGHLANDS State: CO Zip: 80129**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Rezendes, Joe		JoeRezendes@nighthawkenergy.com	
Spear, Sam	(970) 554-1988	samspear@nighthawkenergy.com	
Henkin, Joyce	(303) 407-9609	joycehenkin@nighthawkenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429842	WELL	SI	01/25/2017	OW	073-06477	JOHN CRAIG 6-2	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-638-6096

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	steel panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Heater Treater	# 5		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 3		
Comment:	all pilots on		
Corrective Action:		Date:	
Type: Prime Mover	# 1		

Comment:	gas engine, gas scrubber		Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:	chemical containers		Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLs	STEEL AST		,
Comment:	Check liner integrity (see attached photos inside metal berms at tanks).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	10	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	same berms as produced water tanks			
Corrective Action:				
Date:				

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
------	--

Comment:			
Corrective Action:		Date:	

Location Construction

Location ID: 429842 CDP: _____

Comment: Corrective Action: Date: _____**Form 2A COAs:****Comment:** Corrective Action: Date: _____**Wildlife BMPs:****Comment:** Corrective Action: Date: _____**Comment:** **Corrective Action:** Date: _____**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 429842 Type: WELL API Number: 073-06477 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: [SI since Jun 2015. Form 42 #401256405.](#)

MIT, Pro-Stim Truck

Casing 0 prior to test

0 min 395 psi

5 min 395 psi

10 min 395 psi

15 min 395 psi

Casing 0 after test

[PASSED MIT](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Check Dams	Pass			Check dams are small hay bales

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673715307	Nighthawk John Craig 6-2 MIT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130681