

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/21/2017

Submitted Date:

04/23/2017

Document Number:

680401389**FIELD INSPECTION FORM**

Loc ID 314652 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 100 CHEVRON RDCity: RANGELY State: CO Zip: 81648**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Peterson, Diane	970-675-3842	dlpe@chevron.com	Regulatory Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229199	WELL	TA	11/01/1998	ERIW	103-06286	LEVISON 9	AC

General Comment:UIC-5 yr MIT.

Location**Lease Road:**

Type	Main		
comment:			
Corrective Action	L	Date:	
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 229199 Type: WELL API Number: 103-06286 Status: TA Insp. Status: AC**Underground Injection Control**

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: <u>WEBR</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>06/07/2013</u>
			AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: 5 Year Tbg psi: 1381 Csg psi: 1175 BH psi: 0Insp. Status: PassComment: UIC-5 yr MIT.
Pressure well to 1175 psi. Hold for 15 min. Final pressure 1175 psi. -0 psi loss. OK

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Ditches	Pass			
Berms	Pass	Gravel	Pass	Self Inspection	Pass	

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT