

Inspection Photos

04/24/2017

Operator: DJ Resources Inc #10213

Location ID: 390645

Inspection Doc. Number: 682501923

Logan County, CO

NWSW Section 14 T10N R53W

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: DJ Resources
Location ID: 390645



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: DJ Resources
Location ID: 390645



Photo 2: Photo taken from the northwest end of the location, facing southeast. Photo shows large areas of the location that have not achieved uniform desirable perennial vegetative cover. Inspection doc. 682500992 required to perform reclamation. Unable to find any evidence that reclamation activities had taken place.



Photo 3: Photo taken from the northwest end of the location, facing south. Photo shows large areas of the location that have not achieved uniform desirable perennial vegetative cover. Inspection doc. 682500992 required to perform reclamation. Unable to find any evidence that reclamation activities had taken place.