

Inspection Photos

04/24/2017

Operator: DJ Resources Inc #10213

Location ID: 390646

Inspection Doc. Number: 682501926

Logan County, CO

SESE Section 15 T10N R53W

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: DJ Resources
Location ID: 390646



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: DJ Resources
Location ID: 390646



Photo 2: Photo taken from the east end of the location, facing northwest. Photo shows large areas of the location remain unvegetated, bare and exposed soil.



Photo 3: Photo taken from the east end of the location, facing southwest. Photo shows large areas of the location remain unvegetated, bare and exposed soil. .

Inspection Photos
Operator: DJ Resources
Location ID: 390646



Photo 4: Photo taken from the center of the location. Photo of trash debris remaining on location. Debris appears to be a liner. Other debris such as rags, t-posts and a blackberry cell phone was also found on location.

Inspection Photos
Operator: DJ Resources
Location ID: 390646



Photo 5: Photo taken from the center of the location. Photo shows areas of the location where erosion is occurring. Location has not been adequately stabilized. 6 foot measuring stick for reference.



Photo 6: Photo taken from the west end of the location, facing southeast. Photo shows large areas of the location remain unvegetated, bare and exposed soil.

Inspection Photos
Operator: DJ Resources
Location ID: 390646



Photo 7: Photo taken from the west end of the location, facing east. Photo shows large areas of the location remain unvegetated, bare and exposed soil.



Photo 8: Photo taken from the west end of the location, facing northeast. Photo shows large areas of the location remain unvegetated, bare and exposed soil.