

Photo#1:

Over View of Location from County Rd to SE..



April 22,2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: SWN Williams AL API#107-06258

Photo#2:

View down Access Rd to Location



Photo#3:

View into Location from Entrance




April 22, 2017



Photo#4:  
View South along East side of Pad.



Photo#5:  
View West along North side of Pad



April 22, 2017



Photo#6:

View SW along West side of Pad.



Photo#7:

View East along South side of Pad.



April 22, 2017



Photo#8:

Overview of Location from SE Corner to NW.



April 22,2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: SWN Williams AL API#107-06258